



Snohomish County

Marine Resources Committee

Elisa Dawson, SWM Senior Planner and MRC Staff

8/4/2020

The Snohomish Marine Resources Committee (MRC) is a citizens advisory group to County Government, established in 1999. The MRC is a service of Snohomish County [Surface Water Management](#), a division of the Public Works Department. Surface Water Management provides staff support and funding to the MRC. The [Northwest Straits Initiative](#) also provides funding to the MRC. The MRC's 13 members are appointed by Snohomish County Council and include scientists, local and tribal governments' staff, and individuals representing recreational, economic, and environmental interests.

Northwest Straits Marine Conservation Initiative



Whatcom ♦ Clallam ♦ Jefferson ♦ Skagit ♦ San Juan ♦ Island ♦ Snohomish

MRC Projects

1. Howarth Park Nearshore Restoration
2. MyCoast App
3. Derelict Vessels
4. Recreational Crabber Education
5. Mussel Watch
6. MRC Outreach (Beach Walks, Orca Day, Ocean Literacy)
7. Forage Fish Monitoring
8. Kelp Monitoring
9. Oil Spill Preparedness
10. Port Susan Marine Stewardship Area
11. Snohomish Estuary Pilings Prioritization Project
12. Partnership with SnoCo Parks on Meadowdale Beach Restoration

Today we'll talk about...

1. Howarth Park Nearshore Restoration
2. MyCoast App
3. Derelict Vessels
4. Recreational Crabber Education
5. Mussel Watch
6. MRC Outreach (Beach Walks, Orca Day, Ocean Literacy)
7. Kelp Monitoring
8. Forage Fish Monitoring
9. Oil Spill Preparedness
10. Port Susan Marine Stewardship Area
11. Snohomish Estuary Pilings Prioritization Project (Paul)
12. Partnership with SnoCo Parks on Meadowdale Beach Restoration (Paul)

2017-2018 removed 7 vessels in the Snohomish Estuary/ Everett Nearshore



2020 Plan
to Remove
4 Vessels in
Partnership
with DNR
Derelict
Vessel
Removal
Program



MyCoast App



MyCoast Washington My Account

Abandoned Boat Report by Elisa Dawson



03/09/2020
10:36 am

(2 hours 52 minutes after high tide)



Weather Overview



Wind Speed: 5.5 MPH
Wind Direction: 340°
Temperature: 60°F
Rainfall (Calendar Day): 0.1"
Rainfall (Past 24 Hours): 0.3"

Tidal Overview

Data from [Prest Point](#)
(1.5 miles away)
Water Level: Not yet available
Predicted tide: 5:04 pm, 11.8'

Vessel name: San Diego
Registration Number: Unspecified
Hull Type: Fiberglass
Vessel Type: Recreational
Vessel Subtype: Sailing
Vessel is: Aground
Description of Any Hazardous Materials: Gasoline and batteries
Is Vessel Occupied?: No

Existence of Other Regal Activity: Saw this boat back in December when it was abandoned and tied to a piling. Now it is aground. It appears to be impaled by a piling and is stuck. Not sure if it would float with the tide in low tide.



Weather icons courtesy of [icompl](#). Weather data from [DarkSky](#). Tide data from [NOAA](#).

Report Administration

- ☐ Internal-only
- ☐ Public
- ☒ Public and featured

REASSIGN TO PUBLIC

Reassign to

(Select user)

Abandoned Boat Report by Elisa Dawson

06/16/2020 | 12:57 pm

(2 hours 52 minutes before high tide)



Weather Overview



Wind Speed: 6.6 MPH
Wind Direction: 310°
Temperature: 60°F
Rainfall (Calendar Day): 0.1"
Rainfall (Past 24 Hours): 0.3"

(Click here for full weather details)

Tidal Overview

Vessel name: Unspecified

Registration Number: Wn 1895 JE

Registration Expiration Year: 2015

Hull Type: Fiberglass

Vessel Type: Recreational

Vessel Subtype: Sailing

Vessel is: Afloat

Vessel Secured: Tied but not secure

Is Vessel Occupied?: No

Data from [Prest Point](#) (1.5 miles away)
Water Level: Not yet available
Predicted tide: 8:50 pm, 7.9'



Weather icons courtesy of [icompl](#). Weather data from [DarkSky](#). Tide data from [NOAA](#).

Report Administration

- ☐ Internal-only
- ☐ Public
- ☒ Public and featured

EDIT REPORT

DELETE

VESSEL HAS BEEN REMOVED

Reassign to

(Select user)

Abandoned Boat Report by Elisa Dawson

06/16/2020 | 12:58 pm

(2 hours 52 minutes before high tide)



Weather Overview



Wind Speed: 6.6 MPH
Wind Direction: 310°
Temperature: 60°F
Rainfall (Calendar Day): 0.1"
Rainfall (Past 24 Hours): 0.3"

(Click here for full weather details)

Tidal Overview

Vessel name: Unspecified

Registration Number: Hard to read, maybe wn4560-so

Registration Expiration Year: 2019

Hull Type: Fiberglass

Vessel Type: Recreational

Vessel Subtype: Sailing

Vessel is: Aground

Vessel Secured: Tied but not secure

Description of Any Hazardous Materials: Gas sheen

Is Vessel Occupied?: No



Weather icons courtesy of [icompl](#). Weather data from [DarkSky](#). Tide data from [NOAA](#).

Report Administration

- ☐ Internal-only
- ☐ Public
- ☒ Public and featured

EDIT REPORT

DELETE

VESSEL HAS BEEN REMOVED


Kelp Monitoring 2015-2020

Meadowdale

Mukilteo

Edmonds

Hat Island w/the
Tulalip Tribes



Puget Sound Kelp Conservation and Recovery Plan 2020



Forage Fish


2019: The MRC took 90 forage fish samples at 14 different locations over 12 days of monitoring. Eggs were found at 13 out of 14 sites




2011-2019 focus on Everett Nearshore
Future focus on Meadowdale Project area and
continue monitoring at Howarth Park



West		X		X
2 West				X
2 East				X
3 East 7ft		X	X	X
3 East 10ft		X	X	X
3 West 7ft	X	X	X	X
3 West 10ft	X		X	





Thank you
Questions?

Elisa Dawson
MRC Staff
Senior Planner
Snohomish County
Surface Water Management
elisa.dawson@snoco.org
425-508-2726 (cell)